

Telephone : +66 2287 8202
AFS : VTBDYNYX
Facsimile : +66 2287 8205
E-MAIL : vtbdynyx@aerothai.co.th
www.aerothai.co.th

**THAILAND
INTERNATIONAL NOTAM OFFICE
AERONAUTICAL INFORMATION MANAGEMENT CENTRE
AERONAUTICAL RADIO OF THAILAND
102 NGAMDU-PLÉE, TUNGMAHAMEK
BANGKOK 10120**

**NOTAM LIST
SERIES A**

REFERENCE NO. VTBDYNYX
10/26
1 OCT 2026

The following **NOTAM series A** were **still valid on 1 OCT 2026**, NOTAM not included have either been cancelled, time expired or superseded by AIP supplement or incorporated in the AIP-THAILAND.

VTBB (BANGKOK (ACC/FIC/COM CENTRE))

A3057/26 2609030000/PERM ENR 1.10 FLIGHT PLANNING
4.2.2.2.1 FPL PROC FOR RNAV CAPABLE ACFT DEP AND ARR VTBD, VTBS AND OVERFLYING BKK AMD AS FLW:
15. FM SAGAG TO OVERFLY BKK
(1) PONUK Y27 DUBEN Y28 BKK...
(2) YAKUA B346 BKK...(MON-FRI 0000-0059, 0901-2359 UTC AND SAT SUN, PUBLIC HOLIDAY) THE REST REMAIN UNCHANGED REF AIRAC AIP AMDT 09/26, ENR 1.10-26

A3241/26 2610010000/2610142359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 10/26 WEF 01 OCT 2026.
GEN 0.2 RECORD OF AIP AMDT
GEN 0.4 CHECKLIST OF AIP PAGES
GEN 3.2 ANC
ENR 1.6 ATS SURVEILLANCE SERVICES AND PROC
ENR 1.10 FLIGHT PLANNING

A3352/26 2609030000/PERM SIG POINT ON ATS RTE W26 CHANGED AS FLW:
-KADAV: DIST READ 9NM INSTEAD OF 10NM
-ISKIV: COORD READ 165024N0990229E INSTEAD OF 165044N0990341E, DIST READ 13NM INSTEAD OF 11NM
REF AIRAC AIP AMDT 09/26, ENR 3.1-54, ENR 4.4-2, ENR 6-3

A3448/26 2609030843/2611262359 DUE TO VT D41A ACT FPL PROC FOR ACFT OPR FM/TO VTCC DETAIL AS FLW:
1. PERIOD MON-FRI 0000-1000 EXCLUDING PUBLIC HOLIDAY
DEP/OVERFLY DEST/OVERFLY RTE
VTCC VTCT W12 IKISU W22
VTCC PONUK R207 IKISU W22 CTR A581
VTCT VTCC W22 IKISU W12 PONUK VTCC Y27 DUBEN Y28 CRIST R207 (FOR RNAV)
PONUK VTCC A581 CTR W22 IKISU R207 (FOR NON-RNAV)
2. PERIOD MON-FRI 1001-2359, SAT, SUN, PUBLIC HOLIDAY, H24
DEP/OVERFLY DEST/OVERFLY RTE
VTCC VTCT W20
VTCC PONUK A581
VTCT VTCC W20
PONUK VTCC A581

A3663/26 2610290000/2611112359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 11/26 WEF 29 OCT 2026.
GEN 0.4 CHECKLIST OF AIP PAGES
GEN 3.2 ANC
GEN 4.1 AD/HLP CHARGES
ENR 1.6 ATS SURVEILLANCE SERVICES AND PROC
ENR 3.1 LOWER AND UPPER ATS RTE
ENR 4.4 NAME-CODE DESIGNATORS FOR SIG POINTS
ENR 5.1 PROHIBITED, RESTRICTED, DNG AREAS
ENR 6 ENRC
AD 1.3 INDEX TO AD AND HLP
AD 1.5 STATUS OF CERTIFICATION OF AD

A3669/26 2609190307/2612181659 PURSUANT TO THE COMMUNICABLE DISEASES ACT OF THE KINGDOM OF THAILAND, EFFECTIVE FROM 19 SEPTEMBER 2026 AT 0000 LOCAL TIME (18 SEPTEMBER 2026 AT 1700 UTC) ONWARDS, ALL AIRLINES AND AIR OPERATORS CARRYING PASSENGERS FROM THE DEMOCRATIC REPUBLIC OF THE CONGO (DR CONGO) SHALL COMPLY WITH THE FOLLOWING REVISED MEASURES:
1. PASSENGERS AND CREW MEMBERS DEPARTING FROM DR CONGO ARE PERMITTED TO ENTER THE KINGDOM OF THAILAND EXCLUSIVELY VIA SUVARNABHUMI AIRPORT (VTBS).
2. ALL SUCH PASSENGERS AND CREW MEMBERS SHALL BE SUBJECT TO A MANDATORY QUARANTINE PERIOD OF TWENTY-ONE (21) DAYS, CALCULATED FROM THE DATE OF DEPARTURE FROM THE AFFECTED AREAS, IN ACCORDANCE WITH THE PRESCRIBED PUBLIC HEALTH PROCEDURES AT DESIGNATED QUARANTINE FACILITIES. PASSENGERS AND CREW MEMBERS DEPARTING FROM THE REPUBLIC OF UGANDA SHALL ENTER THE KINGDOM OF THAILAND THROUGH STANDARD IMMIGRATION PROCEDURES, BUT MUST PRESENT A VALID INTERNATIONAL

CERTIFICATE OF VACCINATION AGAINST YELLOW FEVER AT THE PORT HEALTH STATION PRIOR TO IMMIGRATION AND CUSTOMS CLEARANCE. ALL AIRLINES AND AIR OPERATORS CARRYING PASSENGERS FROM THE ABOVE-MENTIONED AREAS ARE REQUESTED TO STRICTLY COMPLY WITH AND IMPLEMENT THESE MEASURES ACCORDINGLY.

A3818/26 2609290257/2612291659 DVOR/DME RYN 112.5MHZ/CH72X U/S

A3820/26 2609290706/2612291659 DUE TO RYN DVOR/DME U/S
ATS RTE W42 B205 AND R334 SHALL CONT TO BE AVBL FOR ACFT APPROVED FOR RNAV2 OPS USING PUBLISHED WGS-84 COORD.

FPL PROC FOR NON RNAV CAPABLE ACFT DETAIL AS FLW:

FM	TO	RTE
VTBS/VTBD	SAKDA/BENSA	DOLNI DCT SAKDA/BENSA...
OVERFLY BKK	SAKDA/BENSA	...BKK DCT SAKDA/BENSA...
SAKDA/BENSA	VTBS	DCT TUMGA
	VTBD	DCT SEHNA
	OVERFLY BKK	DCT BKK...
VTBS/VTBD	VTBO	DOLNI DCT TRT
VTBO	VTBS	DCT TUMGA
	VTBD	DCT SEHNA
VTBU	OVERFLY RAMEI	DCT RUPTA DCT RAMEI...
OVERFLY RAMEI	VTBU	...RAMEI DCT RUPTA DCT
OVERFLY MENEX	OVERFLY RAMEI	...G458 BKK A1 TOPER DCT RAMEI...
OVERFLY RAMEI	OVERFLY MENEX	...W1 BKK G458...

A3843/26 2610010000/2610012359 CDR Y5 (RNAV 2) AVBL FOR FLIGHT PLANNING AS FLW:
PERIOD : MEA LOWER/UPPER LIMITS
0000-0429 FL130/FL460
0430-0530 FL370/FL460
0531-2359 FL130/FL460

VTBD (BANGKOK/DON MUEANG INTL AIRPORT)

A3053/26 2608100451/2611101659 OBST TOWER CRANE HGT 180.45FT AGL ERECTED DETAIL AS FLW:
-AT 135337.60N1003516.20E DIST 730M BFR THR RWY 03L AND 600M LEFT SIDE OF EXTD RCL
-AT 135336.32N1003517.81E DIST 740M BFR THR RWY 03L AND 540M LEFT SIDE OF EXTD RCL

A3466/26 2609070000/2611301659 TXL T BTN TWY W AND TWY V AVBL FOR ACFT UP TO CODE C

A3664/26 2610290000/2611112359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 11/26 WEF 29 OCT 2026.
AD 2-VTBD-1 AD 2.2 AD GEOGRAPHICAL AND ADMINISTRATIVE DATA
AD 2.8 APN, TWY AND CK LCA/PSN DATA
AD 2.10 AD OBST
AD 2.12 RWY PHYSICAL CHARACTERISTICS
AD 2.24 CHARTS RELATED TO AN AD
AD 2-VTBD-2 AD GMC-ICAO

A3751/26 2609250930/PERM AD VTBD 2.24 CHARTS RELATED TO AN AD, IAC-ICAO CHANGED ALT
OCA/H LNAV AS FLW:
1. AD 2-VTBD-8-29 IAC-ICAO-RNP RWY 03L: READ 660(653) INSTEAD OF 590(583)
2. AD 2-VTBD-8-31 IAC-ICAO-RNP RWY 03R: READ 660(655) INSTEAD OF 500(495)
REF AIP AD VTBD 2.24, AD 2-VTBD-8-29, AD 2-VTBD-8-31

A3803/26 2609280411/2610050100 SEQUENCED FLG LGT RWY 03R/21L U/S

VTBS (BANGKOK/SUARNABHUMI INTL AIRPORT)

A3363/26 2608280900/2611260600 ADVANCED VISUAL DOCKING GUIDANCE SYSTEM (A-VDGS)
ACFT STAND NR 119 505 512 AND 520 U/S DUE TO MAINT
RMK: ACFT HAVE TO FLW MARSHALLING SIGNALS STRICTLY

A3415/26 2609011000/2611011000 ACFT STAND NR G3 CLSD DUE TO WIP

A3668/26 2610290000/2611112359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 11/26 WEF 29 OCT 2026.
AD 2-VTBS-1 AD 2.10 AD OBST

A3754/26 2609251056/2610150100 TWY CLSD DUE TO WIP DETAIL AS FLW:
-TWY E BTN TWY D1 AND TWY D2
-TWY D1
-TWY D BEHIND ACFT STAND NR 516-525

A3842/26 2609302030/2610032145 SEP 30 OCT 03 2030-2145 RWY 01/19 CLSD DUE TO WIP

VTBU (RAYONG/U-TAPAO PATTAYA INTL AIRPORT)

A3108/26 2608190100/26111701003 OBST HGT 7FT AGL ERECTED DETAIL AS FLW:

1. CALIBRATE REFLECTOR PSN 124104.08N1010024.24E
(DIST 1227.7M BEYOND THR RWY 18 AND 144.9M LEFT SIDE OF RCL)
2. CALIBRATE REFLECTOR PSN 124042.12N1010021.48E
(DIST 1597M BEYOND THR RWY 36 AND 118.3M RIGHT SIDE OF RCL)
3. OBJECT POSITION AND TRACKING SYSTEM (OPATS) PSN 124052.38N1010016.68E
(DIST 1604.3M BEYOND THR RWY 18 AND 51.6M RIGHT SIDE OF RCL)

A3305/26 2608260637/2610231659 AD CATEGORY FOR FIRE FIGHTING AND RESCUE SERVICES
DOWNGRADED TO CAT 9

A3481/26 2609070100/2611050100 OBST ERECTED DETAIL AS FLW:

1. 2 GENERATORS PSN 124051.98N1010012.45E HGT 4FT AGL DIST 1627.5M BEYOND THR RWY 18 AND 178.4M
RIGHT SIDE OF RCL
2. GROUND CONTROL STATION PSN 124052.53N1010012.44E HGT 8FT AGL DIST 1610.7M BEYOND THR RWY 18 AND 180M
RIGHT SIDE OF RCL
3. GROUND DATA TERMINAL PSN 124053.75N1010012.76E HGT 30FT AGL DIST 1572.5M BEYOND THR RWY 18 AND 173.5M
RIGHT SIDE OF RCL

A3495/26 2609152300/2610311500 OBST MACHINE HGT 65.61FT AGL ERECTED DETAIL AS FLW:
PSN 1: 124041.40N1010022.90E DIST 1585.12M BEYOND THR RWY 36 AND 165.11M RIGHT SIDE OF RCL
PSN 2: 124025.10N1010021.60E DIST 1083.05M BEYOND THR RWY 36 AND 166.06M RIGHT SIDE OF RCL

A3774/26 2609260800/2612251659 PAPI LEFT SIDE RWY 18 U/S

A3805/26 2610051300/2610242300 DAILY 1300-2300
RWY 18/36 CLSD DUE TO CONST EXC ACFT IN STATE OF EMERG

VTCC (CHIANG MAI/CHIANG MAI INTL AIRPORT)

A2622/26 2607150807/2610121000 OBST TOWER CRANE HGT 230FT AGL ERECTED AT
184725.38N0985815.11E DIST 1038M BFR THR RWY 18 AND 854M LEFT SIDE OF EXTD RCL

A3403/26 2609011700/2611301659 OBST MOBILE CRANE HGT 36FT AGL ERECTED AT
184445.10N0985748.00E DIST 795M BFR THR RWY 36 AND 50M RIGHT SIDE OF EXTD RCL,
MARK RED LGT AND FLAG ON TOP

A3665/26 2610290000/2611112359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 11/26 WEF 29 OCT 2026.
AD 2-VTCC-1 AD 2.12 RWY PHYSICAL CHARACTERISTICS

VTCT (CHIANG RAI/MAE FAH LUANG-CHIANG RAI INTL AIRPORT)

A2945/26 2608031133/2610311100 PAPI RIGHT SIDE RWY 21 U/S

A3652/26 2609180900/2610171000 PAPI RIGHT SIDE RWY 03 U/S

A3666/26 2610290000/2611112359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 11/26 WEF 29 OCT 2026.
AD 2-VTCT-1 AD 2.12 RWY PHYSICAL CHARACTERISTICS

A3675/26 2610291500/2611121500 TRIGGER NOTAM-AIRAC AIP SUP A31/26 WEF 29 OCT 2026
TIL 26 MAR 2027. TEMPO CLOSURE OF RWY03/21 FOR REHABILITATION WORKS AT MAE FAH LUANG-CHIANG RAI
INTL AP (VTCT)

A3730/26 2609240446/PERM RWY PHYSICAL CHARACTERISTICS CHANGED AS FLW:
RWY 21 THR ELEV AND HIGHEST ELEV OF TDZ OF PA RWY READ 389M (1275FT) INSTEAD OF 389M (1276FT AMSL)
REF AIP AD VTCT 2.12, AD 2-VTCT-1-5

VTSB (SURAT THANI)

A2879/26 2607310245/2610301659 RWY 04/22 OVERLAY, PARL TWY CONST AND AIRFIELD LGT SYSTEM
REVISION AT VTSB. EXTD TO 30 OCT 2026 AT 1659UTC.
REF AIRAC AIP SUP A51/25

A3243/26 2610010000/2610142359 TRIGGER NOTAM-AIRAC AIP SUP A30/26 WEF 01 OCT 2026 TIL
31 JAN 2027. THE CONST OF PARL TWY AND REVISION OF AIRFIELD LGT SYSTEM AT SURAT THANI AIRPORT (VTSB)

A3672/26 2610290000/2611112359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 11/26 WEF 29 OCT 2026.
AD-2-VTSB-1 AD 2.10 AD OBST
AD 2.12 RWY PHYSICAL CHARACTERISTICS

A3799/26 2609272328/2610280130 AWOS NOT AVBL

A3800/26 2609280020/2610271830 CATIS FREQ 125.95MHZ U/S

VTSG (KRABI)

A2972/26 2608050440/2610242359 AD OPR HR ATS ARO AND MET HR SER CHANGED AS FLW:
AUG 05 0440-1700 2300-2359, 06-OCT 23 0000-1700 2300-2359, 24 0000-1700

A3670/26 2610290000/2611112359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 11/26 WEF 29 OCT 2026.
AD 2-VTSG-1 AD 2.10 AD OBST

VTSM (SURAT THANI/SAMUI)

A3563/26 2609111030/2610301000 ABN U/S

VTSP (PHUKET/PHUKET INTL AIRPORT)

A3114/26 2608170200/2611010600 ACFT STAND NR 7 CLSD DUE TO WIP

A3242/26 2610010000/2610142359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 10/26 WEF 01 OCT 2026.
AD 2-VTSP-1 AD 2.20 LCA AD REGULATIONS

A3637/26 2609171045/PERM ACFT STAND AT APRON E CHANGED AS FLW:
-STAND NR 51 MAX WINGSPAN READ 31.7M INSTEAD OF 30.5M
-STAND NR 52 COORDS READ 080654.19N0981833.73E INSTEAD OF 080653.12N0981835.04E, MAX WINGSPAN
READ 35.9M INSTEAD OF 31M
-STAND NR 52L 52R 53 53L 53R 54 CHANGED TO GA APRON
REF AIP AD2-VTSP-2-3, AD2-VTSP-2-4, AD2-VTSP-2-5

A3667/26 2610290000/2611112359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 11/26 WEF 29 OCT 2026.
AD 2-VTSP-1 AD 2.6 RFFS

A3676/26 2610290000/2611112359 TRIGGER NOTAM AIRAC AIP SUP A32/26 WEF 29 OCT 2026.
REDESIGN OF APN E AND IMPLEMENTATION OF GEN AVIATION APN AT PHUKET INTL AP (VTSP)

A3719/26 2609230325/2610272330 RWY 09/27 OPR BUT CTN ADZ DUE TO FRICTION BLW MNM LEVELS
DIST BTN 2300M-2700M FM THR RWY 09 (TDZ RWY 27 MAY BE SLIPPERY WHEN WET)

A3747/26 2609250748/2610010600 ACFT STAND NR 8 CLSD DUE TO WIP

VTSS (SONGKHLA/HAT YAI INTL AIRPORT)

A3198/26 2608200250/2610282359 TACAN HTY 115.70MHZ/CH104X U/S

A3365/26 2608281000/2611281000 VISUAL DOCKING GUIDANCE SYSTEM (VDGS) ACFT STAND NR 5 U/S

A3376/26 2608301149/2611300200 VISUAL DOCKING GUIDANCE SYSTEM (VDGS) ACFT STAND NR 4 U/S

A3632/26 2609170530/2610170130 TDZ RWY 26 MAY BE SLIPPERY WHEN WET

LATEST PUBLICATIONS AIRAC AIP AMDT: 11/26 WEF 29 OCT 2026

AIP SUPPLEMENT SERIES A VALID PUBLICATIONS:

2017: A40

2023: A04 A28 A29 AND A42

2024: A12 A25 A34 A36 A40 AND A46

2025: A01 A13 A19 A21 A27 A28 A40 A44 A45 A46 A51 A53 AND A57

2026: A01 A02 A03 A12 A16 A18 A19 A20 A21 A23 A24 A25 A26 A27 A29 A30 A31 AND A32/26

AIC VALID PUBLICATIONS:

2022: 1 AND 2

2023: 3

2025: 5 AND 7

2026: 1 2 3 6 7 AND 8

-- END OF SUMMARY --