

Telephone : +66 2287 8202
AFS : VTBDYNYX
Facsimile : +66 2287 8205
E-MAIL : vtbdynyx@aerothai.co.th
www.aerothai.co.th

**THAILAND
INTERNATIONAL NOTAM OFFICE
AERONAUTICAL INFORMATION MANAGEMENT CENTRE
AERONAUTICAL RADIO OF THAILAND
P.O.BOX 34 DON MUEANG
BANGKOK 10211 THAILAND**

**NOTAM LIST
SERIES G**

REFERENCE NO. VTBDYNYX
8/19
01 AUG 2019

The following **NOTAM series G** were **still valid on 08 AUG 2019**, NOTAM not included have either been cancelled, time expired or superseded by AIP supplement or incorporated in the AIP-THAILAND.

VTBD (BANGKOK/DON MUEANG INTL AIRPORT)

G1140/19 1908010059/1908022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1908021420/1908021426
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTBS (BANGKOK/SUVARNABHUMI INTL AIRPORT)

G1141/19 1908010101/1908022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1908021420/1908021426
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTBU (RAYONG/U-TAPAO PATTAYA INTL AIRPORT)

G1139/19 1908010056/1908022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1908021420/1908021427
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTCC (CHIANG MAI/CHIANG MAI INTL AIRPORT)

G1142/19 1908010103/1908022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1908011200/1908011205
1908021156/1908021201
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTCL (LAMPANG)

G1149/19 1908010117/1908022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1908011200/1908011206
1908021156/1908021202
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTCP (PHRAE)

G1150/19 1908010119/1908022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1908011201/1908011207
1908021157/1908021203
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTPH (PRACHUAP KHIRI KHAN/HUA HIN)

G1146/19 1908010111/1908022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1908021420/1908021427
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTPM (TAK/MAE SOT)

G1148/19 1908010116/1908022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1908011155/1908011204
1908021151/1908021200
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTPP (PHITSANULOK)

G1151/19 1908010120/1908022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1908011158/1908011207
1908021154/1908021202
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTSB (SURAT THANI)

G1145/19 1908010110/1908022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1908021418/1908021423
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTSM (SURA TAHNI/SAMUI)

G1144/19 1908010108/1908022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
Page 2 of 3
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1908021418/1908021425
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTSR (RANONG)

G1143/19 1908010105/1908022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1908021418/1908021424
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTUL (LOEI)

G1147/19 1908010114/1908022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1908011202/1908011209
1908021158/1908021205
GPS RAIM UNAVAILABLE FOR RNP APPROACH

LATEST AIRAC AIP AMENDMENT : 9/19 DATED 04 JUL 2019

AIP SUPPLEMENT SERIES A IN FORCE:

2001 : A7	2011 : A4 A7 AND A16
2014 : A14	2016 : A24 AND A31
2017 : A10 A16 A17 A18 A19 A21 A22 A23 A33 AND A40	2018 : A11 A17 AND A21
2019 : A1 A6 A8 A9 A10 A12 A13 A15 AND A16	

AIP SUPPLEMENT SERIES B IN FORCE:

2000 : B8 AND B10	2001 : B7
2003 : B13	2009 : B15
2010 : B1	2017 : B2
2019 : B3 AND B4	

AIC IN FORCE:

2003 : 1	2014 : 1
2016 : 1	2018 : 4 5 6 AND 7
2019 : 1	

-- END OF SUMMARY --