

**THAILAND
INTERNATIONAL NOTAM OFFICE
AERONAUTICAL INFORMATION MANAGEMENT CENTRE
AERONAUTICAL RADIO OF THAILAND
P.O.BOX 34 DON MUEANG
BANGKOK 10211 THAILAND**

**NOTAM LIST
SERIES G**

Telephone : +66 2287 8202
AFS : VTBDYNYX
Facsimile : +66 2287 8205
E-MAIL : vtbdynyx@aerothai.co.th
www.aerothai.co.th

REFERENCE NO. VTBDYNYX
1/19
01 JAN 2019

The following **NOTAM series G** were **still valid on 01 JAN 2019**, NOTAM not included have either been cancelled, time expired or superseded by AIP supplement or incorporated in the AIP-THAILAND.

VTSB (SURAT THANI)

G0002/19 1901010015/1901022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1901010455/1901010500
1901020451/1901020456
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTSF (NAKHON SI THAMMARAT)

G0003/19 1901010018/1901022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1901010455/1901010500
1901020451/1901020456
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTSG (KRABI)

G0004/19 1901010020/1901022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1901010452/1901010500
1901020448/1901020456
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTSP (PHUKET/PHUKET INTL AIRPORT)

G0006/19 1901010024/1901022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1901010451/1901010459
1901020447/1901020455
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTSS (SONGKHLA/HAT YAI INTL AIRPORT)

G0001/19 1901010009/1901022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1901010452/1901010500
1901020448/1901020456
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTST (TRANG)

G0005/19 1901010022/1901022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1901010452/1901010500
1901020448/1901020456
GPS RAIM UNAVAILABLE FOR RNP APPROACH

LATEST AIRAC AIP AMENDMENT : 2/19 DATED 22 DECEMBER 2018

AIP SUPPLEMENT SERIES A IN FORCE :

1999 : A8	2001 : A7
2011 : A4 A7 AND A16	2014 : A14
2016 : A17 A24 A31 AND A32	2017 : A10 A13 A16 A17 A18 A19 A21 A22 A23 A24 A33 AND A40
2018 : A6 A7 A11 A12 A16 A17 A18 A19 A21 AND A22	

AIP SUPPLEMENT SERIES B IN FORCE :

2000 : B8 AND B10	2001 : B7
2003 : B13	2009 : B15
2010 : B1	2017 : B2
2018 : B6 B8 B9 B10 B11 AND B12	

AIC IN FORCE :

2001 : 2	2002 : 1
2003 : 1	2006 : 4
2008 : 2	2014 : 1
2016 : 1 3 AND 6	2018 : 4 5 6 AND 7

-- END OF SUMMARY --