

Telephone : +66 2287 8202
AFS : VTBDYNYX
Facsimile : +66 2287 8205
E-MAIL : vtbdynyx@aerothai.co.th
www.aerothai.co.th

THAILAND
INTERNATIONAL NOTAM OFFICE
AERONAUTICAL INFORMATION MANAGEMENT CENTRE
AERONAUTICAL RADIO OF THAILAND
P.O.BOX 34 DON MUEANG
BANGKOK 10211 THAILAND

NOTAM LIST
SERIES G

REFERENCE NO. VTBDYNYX
6/19
01 JUN 2019

The following **NOTAM series G** were **still valid on 01 JUN 2019**, NOTAM not included have either been cancelled, time expired or superseded by AIP supplement or incorporated in the AIP-THAILAND.

VTCC (CHIANG MAI/CHIANG MAI INTL AIRPORT)

G0592/19 1906010010/1906022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1906011611/1906011616
1906021607/1906021612
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTCL (LAMPANG)

G0594/19 1906010014/1906022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1906011611/1906011616
1906021607/1906021612
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTCP (PHRAE)

G0595/19 1906010017/1906022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1906011612/1906011618
1906021607/1906021614
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTPM (TAK/MAE SOT)

G0593/19 1906010012/1906022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1906011605/1906011610
1906021601/1906021606
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTPP (PHITSANULOK)

G0596/19 1906010020/1906022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1906011609/1906011615
1906021605/1906021611
GPS RAIM UNAVAILABLE FOR RNP APPROACH

VTUL (LOEI)

G0597/19 1906010022/1906022359 GPS RAIM PREDICTION FOR:
TSO-C129 FAULT DETECTION
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION ONLY
NO GPS RAIM OUTAGES
TSO-C146A FAULT DETECTION WITH EXCLUSION
1906011613/1906011620
1906021609/1906021616
GPS RAIM UNAVAILABLE FOR RNP APPROACH

LATEST AIRAC AIP AMENDMENT : 7/19 DATED 09 MAY 2019

AIP SUPPLEMENT SERIES A IN FORCE:

2001 : A7

2014 : A14

2017 : A10 A13 A16 A17 A18 A19 A21 A22 A23 A24 A33 AND A40

2019 : A1 A6 A8 A9 A10 A11 A12 A13 AND A14

2011 : A4 A7 AND A16

2016 : A17 A24 A31 AND A32

2018 : A11 A17 AND A21

AIP SUPPLEMENT SERIES B IN FORCE:

2000 : B8 AND B10

2003 : B13

2010 : B1

2018 : B6

2001 : B7

2009 : B15

2017 : B2

2019 : B1

AIC IN FORCE:

2001 : 2

2008 : 2

2016 : 1 AND 6

2019 : 1

2003 : 1

2014 : 1

2018 : 4 5 6 AND 7

-- END OF SUMMARY --