

Telephone : +66 2287 8202
AFS : VTBDYNYX
Facsimile : +66 2287 8205
E-MAIL : vtbdynyx@aerothai.co.th
www.aerothai.co.th

**THAILAND
INTERNATIONAL NOTAM OFFICE
AERONAUTICAL INFORMATION MANAGEMENT CENTRE
AERONAUTICAL RADIO OF THAILAND
102 NGAMDU-PLÉE, TUNGMAHAMEK
BANGKOK 10120**

**NOTAM LIST
SERIES A**

REFERENCE NO. VTBDYNYX
09/25
1 SEP 2025

The following **NOTAM series A** were **still valid on 1 SEP 2025**, NOTAM not included have either been cancelled, time expired or superseded by AIP supplement or incorporated in the AIP-THAILAND.

VTBB (BANGKOK (ACC/FIC/COM CENTRE))

A1591/25 2506170720/2509170643 A/G FAC BANGKOK APP (VTBS VTBD) FREQ 262.5MHZ OPR FREQ CHANGED TO 274.5MHZ

A2058/25 2509040000/2509172359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 09/25 WEF 04 SEP 2025.
GEN 0.4 CHECKLIST OF AIP PAGES
GEN 2.5 LIST OF RDO NAV AIDS
GEN 3.2 ANC
GEN 3.6 SAR
GEN 4.1 AD/HLP CHARGES
ENR 1.9 ATFM AND AIRSPACE MANAGEMENT
ENR 3.3 RNAV ROUTES
ENR 4.3 GNSS
ENR 4.4 NAME-CODE DESIGNATORS FOR SIG POINTS
ENR 6 ENRC

A2182/25 2508130448/PERM ENR 1.10 FLIGHT PLANNING
4. FPL AND OPR PROC IMPLEMENTED IN BANGKOK FIR
4.2 OPR AND FPL PROC IN THE N AREA OF BANGKOK FIR AMEND AS FLW:
4.2.2.2.2 FPL PROC FOR RNAV CAPABLE ACFT OPR ON WEEKDAYS
(EXCLUDING PUBLIC HOL) BTN 0100-0900UTC
ADD FM VTUL TO VTBD/VTBS :BOVGO B218 CMP W21 NOBER DCT NAKON/NORTA
ADD FM VTUL TO OVERFLY BKK :BOVGO B218 CMP W21 BKK...
4.2.2.2.3 FPL PROC FOR NON RNAV CAPABLE ACFT OPR EXC ON WEEKDAYS
(EXCLUDING PUBLIC HOL) BTN 0100-0900UTC
REVISE FM VTCT TO OVERFLY BKK :DUBEN W29 PSL W9 BKK...
4.2.2.2.4 FPL PROC FOR NON RNAV CAPABLE ACFT OPR ON WEEKDAYS
(EXCLUDING PUBLIC HOL) BTN 0100-0900UTC
ADD FM VTBD/VTBS/OVERFLY BKK TO VTPB :NOBER W21 CMP W26 PCB
ADD FM VTBD/VTBS/OVERFLY BKK TO VLVT :NOBER W21 CMP R474 VTN...
THE REST REMAIN UNCHANGED
REF AIP ENR 1.10, 4.2, 4.2.2.2.2, 4.2.2.2.3, 4.2.2.2.4

A2290/25 2510020000/2510152359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 10/25 WEF 02 OCT 2025.
GEN 0.2 RECORD OF AIP AMDT
GEN 0.4 CHECKLIST OF AIP PAGES
GEN 3.2 ANC
ENR 1.6 ATS SURVEILLANCE SER AND PROC
ENR 1.10 FLT PLANNING
ENR 2.1 FIR UIR AND CTA
ENR 6 ENRC

A2355/25 2508280955/2511151659 TEMPORARY CONSTRUCTION NEAR RAYONG DVOR/DME (RYN)
POSSIBLE IMPACT TO NAVIGATION SIGNAL AND ATS ROUTES
EXTD TO 15 NOV 2025 AT 1659 UTC.
REF AIRAC AIP SUP A32/25

A2378/25 2509010000/2509012359 CDR Y5 (RNAV 2) AVBL FOR FLIGHT PLANNING AS FLW:
PERIOD : MEA LOWER/UPPER LIMITS
0000-0429 FL130/FL460
0430-0530 FL370/FL460
0531-2359 FL130/FL460

VTBD (BANGKOK/DON MUEANG INTL AIRPORT)

A2060/25 2509040000/2509172359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 09/25 WEF 04 SEP 2025.
AD 2-VTBD-1 AD 2.23 ADDN INFO

A2236/25 2509031400/2509031700 SSR U/S DUE TO MAINT

A2291/25 2510020000/2510152359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 10/25 WEF 02 OCT 2025.
 AD 2-VTBD-1 AD 2.18 ATS COM FAC
 AD 2.24 CHARTS RELATED TO AN AD
 AD 2-VTBD-6 SID-ICAO RNAV RWY 21L
 SID-ICAO RNAV RWY 21R
 SID-ICAO RNAV RWY 03L
 SID-ICAO RNAV RWY 03R
 AD 2-VTBD-7 STAR-ICAO RNAV RWY 21L/21R
 STAR-ICAO RNAV RWY 03L/03R
 AD 2-VTBD-8 IAC-ICAO-VOR RWY 21L
 IAC-ICAO-VOR RWY 21R
 IAC-ICAO-VOR RWY 03R
 IAC-ICAO-ILS OR LOC Y RWY 03L
 IAC-ICAO-ILS OR LOC Y RWY 21L
 IAC-ICAO-ILS OR LOC Y RWY 21R CAT II
 IAC-ICAO-ILS OR LOC Z RWY 21L
 IAC-ICAO-ILS OR LOC Z RWY 21R CAT II
 IAC-ICAO-ILS OR LOC Z RWY 03L
 IAC-ICAO-RNP RWY 21L
 IAC-ICAO-RNP RWY 21R
 IAC-ICAO-RNP RWY 03L
 IAC-ICAO-RNP RWY 03R

VTBS (BANGKOK/SUVARNABHUMI INTL AIRPORT)

A1496/25 2506040935/2509022330 TWY F7 CLSD DUE TO WIP

A1583/25 2506160910/2509152330 RAPID EXIT TWY INDICATOR LGT (RETIL) RWY 01/19 U/S

A1584/25 2506160913/2509152330 RAPID EXIT TWY INDICATOR LGT (RETIL) RWY 02R/20L U/S

A1781/25 2507040439/2509181000 PSR U/S

A2063/25 2509040000/2509172359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 09/25 WEF 04 SEP 2025.
 AD 2-VTBS-1 AD 2.20 LCA AD REGULATIONS
 AD 2.24 CHARTS RELATED TO AN AD
 AD 2-VTBS-2 ADC-ICAO
 AD 2-VTBS-3 AOC-ICAO-TYPE A
 RWY 01/19, RWY 02R/20L, RWY 02L/20R
 AD 2-VTBS-8 IAC-ICAO-ILS OR LOC Z
 RWY 01, RWY 02R, RWY 19, RWY 20L CAT II
 IAC-ICAO-RNP
 RWY 01, RWY 02L, RWY 02R, RWY 19, RWY 20L, RWY 20R

A2187/25 2508140505/2510012359 GND MOV CTL FOR ACFT PARKED AT THE FLW STANDS FOR PUSH BACK
 DETAIL AS FLW:
 1. ACFT STAND: B2 B4 B6 C1 C3 C5 C7 C9 201 202 AND 203
 CTC GND CTL FREQ 121.65MHZ
 2. ACFT STAND: E2 E4 E6 E8 E10 F1 F3 F5 401 402 AND 403
 CTC GND CTL FREQ 121.95MHZ
 RMK/PILOT SHALL FLW ATC INSTRUCTIONS STRICTLY

A2213/25 2508151250/2511130300 ADVANCED VISUAL DOCKING GUIDANCE SYSTEM (A-VDGS)
 ACFT STAND NR 520 U/S
 RMK: ACFT HAVE TO FLW MARSHALLING SIGNALS STRICTLY

A2227/25 2508180346/2510012359 TWY CLSD DUE TO WIP DETAIL AS FLW:
 -TWY C BTN TWY C9 AND TWY C10
 -TWY K BTN TWY C AND TWY J4
 -TWY C10

A2287/25 2510020000/2510152359 TRIGGER NOTAM-AIRAC AIP SUP A40/25 WEF 02 OCT 2025 TIL
 02 FEB 2027. THE PARTIAL CLOSURE OF TWY C AND TWY K AT
 SUVARNABHUMI INTL AP(VTBS)

A2292/25 2510020000/2510152359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 10/25 WEF 02 OCT 2025.
 AD 2-VTBS-1 AD 2.18 ATS COM FAC
 AD 2.20 LCA AD REGULATIONS
 AD 2.24 CHARTS RELATED TO AN AD
 AD 2-VTBS-6 SID-ICAO-RNAV RWY 01
 SID-ICAO-RNAV RWY 02L
 SID-ICAO-RNAV RWY 02R
 SID-ICAO-RNAV RWY 19
 SID-ICAO-RNAV RWY 20L
 SID-ICAO-RNAV RWY 20R
 AD 2-VTBS-7 STAR-ICAO-RNAV RWY 01/02L/02R
 STAR-ICAO-RNAV RWY 19/20L/20R
 AD 2-VTBS-8 IAC-ICAO-ILS OR LOC Z RWY 01 CAT II
 IAC-ICAO-ILS OR LOC Z RWY 02R CAT II
 IAC-ICAO-ILS OR LOC Z RWY 19 CAT II
 IAC-ICAO-ILS OR LOC Z RWY 20L CAT II
 IAC-ICAO-RNP RWY 01
 IAC-ICAO-RNP RWY 02L
 IAC-ICAO-RNP RWY 02R
 IAC-ICAO-RNP RWY 19
 IAC-ICAO-RNP RWY 20L
 IAC-ICAO-RNP RWY 20R

VTBU (RAYONG/U-TAPAO PATTAYA INTL AIRPORT)

A1731/25 2507010500/2510011659 OBST TOWER CRANE HGT 330FT AGL ERECTED AT
 124008N1005952E DIST 530M BEYOND THR RWY 36 AND 680M LEFT SIDE OF RCL MARKED RED LGT ON TOP

A2064/25 2509040000/2509172359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 09/25 WEF 04 SEP 2025.
 AD 2-VTBU-1 AD 2.2 AD GEOGRAPHICAL AND ADMINISTRATIVE DATA
 AD 2.12 RWY PHYSICAL CHARACTERISTICS
 AD 2.24 CHARTS RELATED TO AN AD
 AD 2-VTBU-2 ADC-ICAO
 AD GND MOV CHART-ICAO
 AD 2-VTBU-3 AOC-ICAO-TYPE A RWY 18/36

A2245/25 2508191701/2511201659 AD CATEGORY FOR FIRE FIGHTING AND RESCUE SERVICES
 DOWNGRADED TO CAT 9

A2272/25 2508220300/2511201659 SALS RWY 36 AND PALS RWY 18 U/S

VTCC (CHIANG MAI/CHIANG MAI INTL AIRPORT)

A1795/25 2507070440/2510041000 OBST TOWER CRANE HGT 230FT AGL ERECTED AT
 184723.00N0985808.30E DIST 1030M BFR THR RWY 18 AND 670M LEFT SIDE OF EXTD RCL, MARKED RED LGT ON TOP

A2061/25 2509040000/2509172359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 09/25 WEF 04 SEP 2025.
 AD 2-VTCC-1 AD 2.23 ADDN INFO

VTCT (CHIANG RAI/MAE FAH LUANG-CHIANG RAI INTL AIRPORT)

A2995/24 2410170445/PERM RWY TURN PAD AT THE END OF RWY 21 USED ONLY FOR ACFT WITH
 OUTER MAIN GEAR WHEEL SPAN (OMGWS) LESS THAN 9M UNTIL PUBLISHED ON AIP AMDT

A2111/25 2508060902/2511031659 OBST MOBILE CRANE HGT 195FT AGL ERECTED DETAIL AS FLW:
 1. 195551.42N0995149.49E
 DIST 1525M BFR THR RWY 03 AND 610M LEFT SIDE OF EXTD RCL
 2. 195554.77N0995149.48E
 DIST 1505M BFR THR RWY 03 AND 660M LEFT SIDE OF EXTD RCL

A2241/25 2508190320/2511191000 OBST ELECTRIC POLE HGT 150FT ERECTED DETAIL AS FLW:
 PSN 1: 195527.10N0995143.50E (DIST 2555M BFR THR RWY 03
 AND 395M LEFT SIDE OF EXTD RCL)
 PSN 2: 195531.90N0995144.60E (DIST 2135M BFR THR RWY 03
 AND 435M LEFT SIDE OF EXTD RCL)

A2288/25 2510020000/2510152359 TRIGGER NOTAM-AIRAC AIP SUP A46/25 WEF 02 OCT 2025.
 RESTRICTION ON TURN PAD AT THE END OF RWY 21 AT
 MAE FAH LUANG-CHIANG RAI INTL AP(VTCT)

A2289/25 2510020000/2510152359 TRIGGER NOTAM-AIRAC AIP SUP A47/25 WEF 02 OCT 2025 TIL 24 DEC 2025. THE REMAINING CONSTRUCTION OF NEW TAXIWAYS AND THE CLOSURE OF TWY A AT MAE FAH LUANG-CHIANG RAI INTL AP(VTCT)

A2330/25 2508260312/2509261500 TWY C CLSD DUE TO WIP
RMK: ALL ACFT LANDED RWY 03 WILL BE REQUIRED TO PLAN FOR VACATING RWY VIA TWY A OR TWY B
IN CASE OF TRAFFIC ON TWY A AND UNA TO VACATE AT TWY B,
ACFT CODE LETTER C OR BLW ARE ALLOWED TO DO 180DEG TURN ON THE RWY FLW ATC INSTRUCTIONS

A2354/25 2510020000/2510302259 THE REMAINING CONSTRUCTION OF NEW TAXIWAYS AND THE CLOSURE OF TAXIWAY A AT MAE FAH LUANG-CHIANG RAI INTERNATIONAL AIRPORT.
ITEM 4.2.3 THE DECLARED DIST AMEND AS FLW:
RWY TORA(M) TODA(M) ASDA(M) LDA(M)
21 2150 2150 2150 3000
REF AIRAC AIP SUP A47/25

VTSB (SURAT THANI)

A1673/25 2506250530/2509251100 DUE TO THE CONST, THE WIDTH OF STRIP WILL BE REDUCED FM 150M TO 100M FM RCL. THE CONST AREA COVERS THROUGHOUT THE LEN OF 3000M FM RWY END ON THE RIGHT SIDE OF THR RWY 04 TO THR RWY 22

A1674/25 2506250709/2509251100 TWY A AND TWY B CLSD DUE TO WIP

A1775/25 2507030925/2510031000 ILS GP FREQ 332.6MHZ RWY 22 U/S

A2003/25 2507290900/2510291500 ACFT STAND NR 2 CLSD

A2294/25 2510020000/2510152359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 10/25 WEF 02 OCT 2025.
AD 2-VTSB-1 AD 2.2 AD GEOGRAPHICAL AND ADMINISTRATIVE DATA
AD 2.8 APRONS, TAXIWAYS AND CK LOCATIONS/POSITIONS DATA
AD 2.24 CHARTS RELATED TO AN AD
AD 2-VTSB-2 ADC-ICAO
AD 2-VTSB-3 AOC-ICAO TYPE A-RWY 04/22

VTSG (KRABI)

A2221/25 2508170403/2510170400 RVR RWY 14 U/S

A2293/25 2510020000/2510152359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 10/25 WEF 02 OCT 2025.
AD 2-VTSG-1 AD 2.2 AD GEOGRAPHICAL AND ADMINISTRATIVE DATA
AD 2.24 CHARTS RELATED TO AN AD
AD 2-VTSG-2 ADC-ICAO
AD 2-VTSG-3 AOC-ICAO TYPE A-RWY 14/32

VTSM (SURAT THANI/SAMUI)

A2295/25 2510020000/2510152359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 10/25 WEF 02 OCT 2025.
AD 2-VTSM-1 AD 2.2 AD GEOGRAPHICAL AND ADMINISTRATIVE DATA
AD 2.24 CHARTS RELATED TO AN AD
AD 2-VTSM-2 ADC-ICAO
APDC-ICAO
AD GMC-ICAO
AD 2-VTSM-3 AOC-ICAO TYPE A-RWY 35/17

VTSP (PHUKET/PHUKET INTL AIRPORT)

A1141/25 2504240950/PERM VASIS (MEHT) PAPI AMD AS FLW:
(1)RWY DESIGNATOR (4)VASIS (MEHT) PAPI
09 PAPI BOTH 3 DEGREE 66.67 FT
27 PAPI BOTH 3.2 DEGREE 55.11 FT
REF AIP AD 2-VTSP-1-7, VTSP AD 2.14

A1903/25 2507170853/2510171000 SEQUENCED FLG LGT RWY 27 U/S

A1952/25 2507220940/2510220500 OBST TREE ERECTED DETAIL AS FLW:
1. 080638.32N0981807.70E HGT 16.40FT AGL DIST 140M BFR THR RWY 09, 130M RIGHT SIDE OF EXTD RCL
2. 080647.51N0981808.25E HGT 19.68FT AGL DIST 97M BFR THR RWY 09, 147M LEFT SIDE OF EXTD RCL

A2062/25 2509040000/2509172359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 09/25 WEF 04 SEP 2025.
AD 2-VTSP-1 AD 2.23 ADDN INFO
AD 2.24 CHARTS RELATED TO AN AD
AD 2.6 RFFS
AD 2-VTSP-8 IAC-ICAO-VOR Y RWY 09, RWY 27
IAC-ICAO-VOR Z RWY 09, RWY 27
IAC-ICAO-ILS OR LLZ RWY 27
IAC-ICAO-RNP Z RWY 09, RWY 27
IAC-ICAO-RNP Y RWY 09, RWY 27

A2065/25 2509040000/2509172359 TRIGGER NOTAM-PERM AIRAC AIP AMDT 09/25 WEF 04 SEP 2025.
AD 2-VTSS-1 AD 2.6 RFFS
AD 2.23 ADDN INFO

A2260/25 2508201028/2510201100TWY EDGE LGT U/S DUE TO WIP DETAIL AS FLW:
-TWY J
-TWY K
-TWY L
-TWY M

A2298/25 2510020100/2510160100 TRIGGER NOTAM-AIRAC AIP SUP A39/25 WEF 02 OCT 2025 TIL
31 OCT 2026. RWY 09/27 CLOSURE FOR MAINT WORKS AT
PHUKET INTL AP(VTSP)

A2366/25 2509010100/2509010500 ACFT STAND NR 1 CLSD DUE TO WIP

VTSS (SONGKHLA/HAT YAI INTL AIRPORT)

A1833/25 2507100857/2509101000 TACAN HTY 115.70MHZ/CH104X ON TEST, DO NOT USE

LATEST PUBLICATIONS AIRAC AIP AMDT : 10/25 WEF 2 OCT 2025

AIP SUPPLEMENT SERIES A VALID PUBLICATIONS :

2017: A40

2023: A4 A28 A29 AND A42

2024: A12 A16 A17 A25 A29 A34 A36 A40 A46 A49 A53 AND A54

2025: A1 A4 A9 A13 A16 A18 A19 A21 A26 A27 A28 A30 A32 A33 A34 A35 A37 A39 A40 A41 A42 A43 A44 A45 A46 A47

AIC VALID PUBLICATIONS :

2022: 1 AND 2

2023: 3

2024: 5 7 AND 9

2025: 1 2 3 4 5 6 AND 7

-- END OF SUMMARY --